

| GROUP NO. — DESCRIPTION — YEAR and MODEL | PRIMARY GROUP NO. | PER CAR | PART NO. | CODE |
|---|-------------------|---------|----------|------|
| 61-62 01 (LHE-WST Export 3-3/4" Stroke)(LHE-WOD Export 3-3/4" Stroke) | | 1 | 320 2936 | |
| 62 01 (LHE) | | 1 | 320 3319 | |
| 62 01 (OHV) | | 1 | 320 3324 | |
| 63 01 (LHE) | | 1 | 320 3979 | |
| 63 01-10 (OHVC) | | 1 | 320 3929 | |
| 64 01 (LHE) | | 1 | 320 4681 | |
| 64 01-10 (OHVC-196) | | 1 | 320 4682 | |
| 65 01 (LHE) | | 1 | 320 5603 | |
| 65 01 (OHV-196) | | 1 | 320 5604 | |
| 65 01-80 (OHV-232): 64-65 10 (OHV-232): 65 01-10 (OHV-199) | | 1 | 320 5432 | |
| 61-62 10 (OHVA) (Use 320 3980) | | 1 | 320 2543 | |
| 63-64 10 (OHVA) | | 1 | 320 3980 | |
| 63 Thru 65 10 (V8-287): 65 80 (V8-287) | | 1 | 320 4559 | |
| 60-61 20 | | 1 | 320 0557 | |
| 60 Thru 62 80 | | 1 | 320 2146 | |
| 64-65 10 (V8-327): 63 Thru 65 80 (V8-327) | | 1 | 320 3950 | |

PIN, Cylinder Block To Clutch Housing Or Converter Housing Dowel

| | | | |
|--|---|----------|---|
| 65 01-80 (OHV-232): 65 01-10 (OHV-199): 64-65 10 (OHV-232): 60 Thru 65 10-20-80 (V8) | 2 | 314 5091 | # |
| 60 Thru 65 10-20-80 (V8) | 2 | 314 4842 | |

PIN, Cylinder Block To Timing Case Cover Dowel

| | | | |
|------------------------------------|---|----------|---|
| 60 Thru 65 10-20-80 (V8) | 2 | 314 4842 | # |
|------------------------------------|---|----------|---|

PIN, Cylinder Block To Cylinder Head Dowel

| | | | |
|------------------------------------|---|----------|--|
| 60 Thru 65 10-20-80 (V8) | 4 | 314 4842 | |
|------------------------------------|---|----------|--|

BAFFLE, Engine Breather Chamber Oil Deflector

| | | | |
|--------------------------------|-------|---|----------|
| 61 Thru 63 10 (OHVA) | 1.115 | 1 | 316 2016 |
|--------------------------------|-------|---|----------|

ATTACHING PARTS

Baffle To Block

| | | | |
|--|--------|---|------------|
| BOLT, Hexagon 61 Thru 63 10 (OHVA) | 17.038 | 1 | G180020 NA |
| WASHER, Fibre 61 Thru 63 10 (OHVA) | 1.115 | 1 | 316 1263 |
| NUT, Lock 61 Thru 63 10 (OHVA) | 17.416 | 1 | G442823 NA |

SEPARATOR, Engine Breather Chamber Oil

| | | | |
|--------------------------------|-------|---|----------|
| 61 Thru 63 10 (OHVA) | 1.115 | 1 | 316 2017 |
|--------------------------------|-------|---|----------|

1.022 PIPE, Oil Filler

| | | | |
|--|--|---|----------|
| 60 Thru 63 01 (LHE) | | 1 | 310 6489 |
| 60-61 01-10 (OHVC): 62-63 01 (OHV-LPB): 62 Thru 64 10 (OHVC-196-LPB-Note 1.022-3 Type 1) | | 1 | 315 2734 |
| 62-63 01-10 (LHD-OHVC-WPB) | | 1 | 316 4768 |
| 64-65 01 (LHE) | | 1 | 317 2622 |
| 64-65 01 (OHVC-196): 64 10 (OHVC-196-Note 1.022-4) | | 1 | 317 1080 |
| 64 10 (OHVC-WPB-Note 1.022-3) | | 1 | 317 1927 |

ATTACHING PARTS

Pipe To Block

| | | | |
|---|--------|---|----------|
| SCREW, Machine 60 Thru 65 01 (OHVC-196): 60 Thru 64 10 (OHVC) (Replaces 800 0068) | 17.626 | 1 | 400 0987 |
|---|--------|---|----------|

- NOTE 1.022-1: On 63 01 (OHV-LDT) used prior to Car Sequence No. 40006.
- NOTE 1.022-2: On 63 01 (OHV-LDT) used beginning with Car Sequence No. 40006.
- NOTE 1.022-3: On 64 10 (OHVC-196) used prior to Engine Code No. 604-C-12.
- NOTE 1.022-4: On 64 10 (OHVC-196) used beginning with Engine Code No. 604-C-12.